

# FOJST Instruction Sheet


**Warning!** This tool should not be used on live electrical circuits. It is not protected against electrical shock! Always use OSHA/ANSI or other industry approved eye protection when using tools. This tool is not to be used for purposes other than intended. Read carefully and understand instructions before using this tool.

The Miller FOJST tool is a compact, one-step jacket slitter for PVC jacketed fiber cables. The tool will produce two jacket slits 180 degrees apart as required for certain fiber connectors. The quality design provides reliable, nick-free slitting preparations. Two FOJST tool models are available. One is for 2mm or 3mm jacketed cable, and another for 1.6mm or 2.4 mm jacketed cable.

The slitting cassettes are identified by size and are made with indicator marks for achieving accurate prep lengths.

- Insert the cable in the proper opening. Use the indicator marks to position the cable.
- Close the tool and pull it off the cable for the desired dual slit.

FOJST 2mm / 3mm    Part No. 81210  
FOJST 1.6mm/2.4mm    Part No. 81215



WARRANTY: RIPLEY warrants its products against defective materials and workmanship for a period of one year from date of shipment from the RIPLEY factory provided the product is utilized in accordance with instructions and specified ratings.



46 Nooks Hill Road, Cromwell, CT 06416 USA ~ Phone: 800-528-8665 ~ Int'l: (01) 860-635-2200  
Fax: (01) 860-635-3631 ~ E-mail: [info@ripley-tools.com](mailto:info@ripley-tools.com) ~ Internet: [www.ripley-tools.com](http://www.ripley-tools.com)



81214  
10-19-15ff